PRODUCT DATASHEET

# **1000A Clamp Meters with IR Thermometers**

Clamp-on multimeter with built-in non-contact InfraRed Thermometer

Ideal for industrial applications the 800 series Full size 1000A clamps feature a built-in Infared thermometer and rugged double molded housing.

## **EX800 Series Features:**

- Non-contact InfraRed Temperature measurements with laser pointer
- Models with True RMS Current and Voltage measurements
- Peak hold captures inrush currents and Transients
- MultiMeter functions include AC/DC Voltage, Resistance, Capacitance, Frequency, Diode, and
- 1.7" (43mm) jaw opening for conductors up to 750MCM or two 500MCM
- 4000 count backlit display
- Features include Data Hold and Min/Max
- · Autoranging with manual range button
- Auto Power off
- Complete with test leads, 9V battery, Type K probe (-22 to 572°F/-30 to 300°C) for EX820/EX830, and case

#### Model EX810

- AC Current
- Average responding

## Model EX820

- AC Current
- True RMS
- Type K thermometer

### Model EX830

- DC/ AC Current
- True RMS
- Type K thermometer
- DC Zero





True RMS meter gives you accurate readings of non-sinusoidal waveforms



troubleshooter for locating hot spots and overheating motors.



Complete with test leads. 9V battery, type K probe (EX820/EX830) and belt holster



S H	28	200	203	
Specifications	EX810	EX820	EX830	Basic Accuracy
IR Temperature (IR)	<ul> <li>✓ -58 to 518°F</li> <li>-50 to 270°C</li> </ul>	<ul> <li>✓ -58 to 518°F</li> <li>-50 to 270°C</li> </ul>	<ul> <li>-58 to 518°F</li> <li>-50 to 270°C</li> </ul>	✓ ±2.0% rdg or ±4°F/±2°C
AC Current	0.1 to 1000A	0.1 to 1000A	0.1 to 1000A	2.8% (EX810) 2.5% (EX820, EX830)
DC Current	_	_	✓ 0.1 to 1000A	±2.5%
AC Voltage	0.1mV to 600V	0.1mV to 600V	0.1mV to 600V	±1.8% (EX810) ±1.5% (EX820, EX830)
DC Voltage	0.1mV to 600V	0.1mV to 600V	0.1mV to 600V	±1.5%
Resistance	0.1 to 40MΩ	0.1 to 40MΩ	0.1 to 40MΩ	±1.5%
Capacitance	0.001nF to 40,000μF	0.001nF to 40,000μF	0.001nF to 40,000μF	±3.0%
Frequency	0.001kHz to 4kHz	0.001kHz to 4kHz	0.001kHz to 4kHz	±1.5%
Type K Temperature	_	<ul><li>✓ -4 to 1400°F</li><li>-20 to 760°C</li></ul>	<ul><li>✓ -4 to 1400°F</li><li>-20 to 760°C</li></ul>	±(3%rdg+9°F/5°C)
Continuity	Yes	Yes	Yes	
Inrush	Yes	Yes	Yes	
Diode	Yes	Yes	Yes	
Dimensions	10.6x4.3x2"	10.6x4.3x2"	10.6x4.3x2"	

(270x110x50mm)

13.6oz (386g)

(270x110x50mm)

13.6oz (386g)

# **Ordering Information:**

......1000A AC Clamp/DMM+IR Thermometer

EX810-NISTL\* .......1000A AC Clamp/DMM+IR Thermometer w/NIST Certificate

......1000A AC True RMS Clamp/DMM+IR Thermometer

EX820-NISTL\* .......1000A AC True RMS Clamp/DMM+IR Thermometer w/NIST Certificate

EX830 ......1000A AC/DC True RMS Clamp/DMM+IR Thermometer

EX830-NISTL\* ......1000A AC/DC True RMS Clamp/DMM+IR Thermometer w/NIST Certificate \*NISTL is a Limited NIST: Product is certified to all functions except IR Thermometer



Weight





(270x110x50mm)

13.6oz (386g)



